

Harness inspection certificate - EN

Inspection certificate number: PH_293.2020

Impact pad number: PH_293.2020

Manufacturer data

Manufacturer name: **Neo SAS**
 Representative: **Eric Roussel**
 Street: **ZA des Vernays**
 Post code / place: **74210 Doussard**
 Country: **France**

Sample data:

Harness

Impact pad

Name:	Bikini	Name Impact pad: ⁽¹⁾	n/a
Type:	ABS	Impact pad integrated: ⁽¹⁾	Yes
Size:	SM	Impact pad type:	Koroyd
Weight of Sample [kg]:	2.74	Weight of Sample [kg]: ⁽¹⁾	0.305
Serial number:	H12002	Serial number: ⁽¹⁾	n/a
Clip-in weight [kg]:	120		
Integrated container for rescue system:	Yes	Date of reception:	07.02.2020
Volume container [cm ³]:			
			n/a max
			n/a min
Date of reception:	07.02.2020		


Test report summary

Structual test

Impact pad test

Result	POSITIVE	POSITIVE
Place	Villeneuve	Villeneuve
Date	07.02.2020	07.02.2020

Issue data

Place of declaration: **Villeneuve**
 Date of issue: **23.07.2020**
 Managing Director: **Alain Zoller**
 Signature: 

This signature approve the validity of the test reports if available; no. 94.21b (test id 01,03,05,06,08,09,10,11,12,14,RRDT,RRST) and no. 94.22 (test id: P,PR)
Air Turquoise SA, having thoroughly assessed the sample mentioned above, declare it was found conform with all requirements defined by the following norms:

European Standard EN1651:2018, and EN12491:2015

⁽¹⁾ If Impact pad is NOT integrated in the harness, it will have independently Inspection number, and serial number. Definition of integrated impact pad is impact pad which can not be dismantled from the harness, e.g. airbag.

Present declaration's scope only extends to the conformity of a given sample, on a given date and in a given place – as mentioned here above.

This inspection certificate contain the following test and is complet with the test, if available, report: 94.21 and 94.22