

Safety notice (EN) | NEO Container

Doussard (France), January 15, 2018

The handle of the external NEO Container can loose the connexion with its pin (plastic rod).
The problem may happen after several month or year of use.



To solve this problem, NEO is replacing all rescue handles of the NEO Container delivered.
The original handle, on the left, is replaced by this new one, on the right :



Thanks to contact your dealer to get your rescue container handle replacement:

<http://www.flyneo.com/en/dealers/>

Info sécurité (FR) | NEO Container

Doussard, le 15 janvier 2018

La poignée du Container externe de parachute de secours NEO peut se désolidariser de son jonc. Ce problème peut arriver après plusieurs mois ou années d'utilisation.



Pour résoudre le problème, NEO remplace toutes les poignées de secours.

La poignée d'origine, ici à gauche, sera remplacée par la nouvelle poignée à droite :



Merci de contacter votre revendeur pour obtenir votre poignée de remplacement :

<http://www.flyneo.com/revendeurs/>